

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE (ER 1130-2-3165)					PAGE 1 OF 1		
					DATE October 20, 2004		
TO: The Record				FROM: U.S. Army Corps of Engineers 26 Federal Plaza, ATTN: CENAN-OP-ST New York, NY 10278-0090			
Moriches Inlet, New York					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nmiles)	DEPTH (feet)			
Moriches Inlet	File # 45, 30 Sep-1 Oct 2004	200	.61	10	3.9	3.8	3.7
REMARKS: All depths in Mean Low Water (MLW). Recent reports from the U.S. Coast Guard indicate severe shoaling in the center of the inlet creating a hazardous situation.							